

Recognition of MTM Safeworking Competencies in RIW



As advised in Safety Bulletin **010/21**, Vline has been made aware that the current MTM infrastructure safeworking training courseware relevant to the Level **2.1/2.2** (Lookout/Hand Signaller) and **TFPC3.2** competencies is deficient in specific areas of safeworking detail. These deficiencies relate to safeworking processes unique to the Vline Network.

As a result, effective from **Friday 16.04.21**, MTM safeworking training (both initial and refresher) delivered from this date will no longer be considered acceptable evidence in RIW. This will negate the following roles and associated competencies:

Role:

V/line - Track Force Protection Coordinator **Level 3:3** Certificate of Currency

Competency

V/line - Track Force Protection Coordinator Level 3:3 (47192)

Role:

V/line - Track Force Protection Coordinator **Level 3:2** Certificate of Currency

Competency:

V/line - Track Force Protection Coordinator Level 3:2 (47191)

Role:

V/line - Track Protection – Hand Signaller **Level 2:2** Certificate of Currency

Competency:

V/line - Track Protection – Hand Signaller Level 2:2 (47189)

Vline approved training providers for these competencies can be found on the Rail Industry Worker website – www.riw.net.au

David Ward
Safeworking Manager Network Maintenance